

Date : 02/21/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 02/21/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 57198
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Partly Cloudy
Departure Time : 02/21/2023 16:30
ASEC Technician Name : Vidal Dias

Our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Vidal Dias visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to monitor, verify and document the ongoing project activities.

During the visit, the following observations were made:

1. Five (5) loads and 128.16 tons of riprap were delivered.
2. Additional rip-rap was placed in area F7
3. Three rolls of geogrid were placed in the lower half of the basement.
4. Geogrid was placed according to the project specifications noted on drawing #E720667

Photo documentation is included below:



Date : 02/21/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 02/21/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 57198
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Partly Cloudy
Departure Time : 02/21/2023 16:30
ASEC Technician Name : Vidal Dias



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.