



Date : 03/13/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 03/13/2023 06:00
Onsite Hours : 10:00

ASEC Report ID : 57749
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Partly Cloudy
Departure Time : 03/13/2023 16:00
ASEC Technician Name : Vidal Dias

Our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Vidal Dias visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to observe, verify and document the ongoing project activities. During the visit, the following observations were made:

1. 803.85 tons (33 loads) of 825B were received and placed in sections (H6, G6, and F6). The materials were placed in accordance with ITP-003.
2. Terra fabric was placed in area F6 and overlain with 825B in accordance with ITP-003.
3. Four (4) compaction tests were performed, and compaction test locations are labeled on the attached drawing. Tests were conducted per ITP-003 and were within the scope of the recommendations listed in ITP-003.

Photo documentation is included below:



Date : 03/13/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 03/13/2023 06:00
Onsite Hours : 10:00

ASEC Report ID : 57749
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Partly Cloudy
Departure Time : 03/13/2023 16:00
ASEC Technician Name : Vidal Dias



Vidal Dias
070321636
Project Geologist



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.