

Date : 03/14/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 03/14/2023 06:00
Onsite Hours : 10:15

ASEC Report ID : 57806
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Sunny
Departure Time : 03/14/2023 16:15
ASEC Technician Name : Vidal Dias

Our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Vidal Dias visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to observe, verify and document the ongoing project activities. During the visit, the following observations were made:

1. Seven hundred ninety-two (792) yards (44 loads) of fill material was received and placed in the south portion of the basement, section 10. The fill material was placed in accordance with ITP-001.
2. 825B was placed in areas G6 and F6 in accordance with ITP-003.

Photo documentation is included below:




Area G6



Date : 03/14/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 03/14/2023 06:00
Onsite Hours : 10:15

ASEC Report ID : 57806
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Sunny
Departure Time : 03/14/2023 16:15
ASEC Technician Name : Vidal Dias



Vidal Dias
070321636
Project Geologist



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.