

Date : 03/24/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 03/24/2023 06:00
Onsite Hours : 10:30


ASEC Report ID : 58062
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather :
Departure Time : 03/24/2023 16:30
ASEC Technician Name : Vidal Dias

Our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Vidal Dias visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to observe, verify and document the ongoing project activities. (Reference drawing E720661 S1 - R5, E720659 S1-R5.)

During the visit, the following observations were made:

1. Fifty-eight (58) loads of fill material were delivered, and one thousand forty-four (1044) cubic yards of fill material were placed in the basement for the two-foot bridge lift.
2. The placement and compaction of the fill materials are in accordance with ITP-001.
3. Additional compaction of fill material was conducted with a CAT CS54B roller.
4. Rip-rap was placed along the eastern-facing retaining wall in sections F6 and G6 (drawing E720659 S1-R5). The area is highlighted in red on the attached drawings.
5. Rip-rap was placed in accordance to ITP-003

Photo documentation and test locations are attached:



Date : 03/24/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 03/24/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 58062
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather :
Departure Time : 03/24/2023 16:30
ASEC Technician Name : Vidal Dias



Vidal Dias
070321636
Project Geologist



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.