

Date : 04/05/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 04/05/2023 06:00
Onsite Hours : 10:00



ASEC Report ID : 58484
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Partly Cloudy
Departure Time : 04/05/2023 16:00
ASEC Technician Name : Vidal Dias

AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Vidal Dias visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to monitor, verify and document the ongoing project activities. (reference drawing E720661 S1 - R5, E720659 S1-R5.)

During the visit, the following observations were made:

1. Two thousand one hundred sixteen cubic yards of fill materials were placed in sections 1 & 2
2. The fill material was placed in general accordance with ITP-001. The area was probed, and two density tests were performed in section 1, area B7 (E720661 S1 - R5).
3. Photo locations are labeled on the attached drawing. The placement area is shaded in purple on the attached drawing.

Photo documentation and test locations are attached:



Date : 04/05/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 04/05/2023 06:00
Onsite Hours : 10:00

ASEC Report ID : 58484
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Partly Cloudy
Departure Time : 04/05/2023 16:00
ASEC Technician Name : Vidal Dias



Vidal Dias
070321636
Project Geologist



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.