

Date : 08/14/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 08/14/2023 08:15
Onsite Hours : 08:45

ASEC Report ID : 60816
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Clear skies
Departure Time : 08/14/2023 17:00
ASEC Technician Name : Ramchandra Mogulla

AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Ram Mogulla visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to observe, verify and document the ongoing project activities. (reference drawing E720661 S1 - R5, E720659 S1-R5.)


During the visit, the following observations were made:

1. Two thousand five hundred thirty-eight (2538) cubic yards of fill material was received and placed as lift (26) in section 2 and lift 28 of section 1, basement area G7 (drawing E720661) of the basement. The materials were placed and compacted in general accordance with ITP-001.
2. A total of 3 nuclear density tests and a Proctor check were performed on this day. Testing was performed on Lift 27 in section 1 and lift 26 of section 2. Testing locations and test results are reported in a stand-alone report.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Compaction efforts



Sealing operations

Date : 08/14/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 08/14/2023 08:15
Onsite Hours : 08:45

ASEC Report ID : 60816
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Clear skies
Departure Time : 08/14/2023 17:00
ASEC Technician Name : Ramchandra Mogulla



General site view



Testing performed



Ramchandra Mogulla, PE
31220
Senior Engineer

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.