

Date : 09/22/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 09/22/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 61932
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : SUNNY
Departure Time : 09/22/2023 16:30
ASEC Technician Name : Avinash Bandham

AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Avinash Bandam visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to monitor, verify and document the ongoing project activities. (Reference drawing E720661 S1 - R8, E720659 S1-R8.)

1. Hauling in the Basement was performed in section 1 for a lift (10) and Section 2 for a lift (14).
2. Transportation of clay materials has been stopped because basement has been filled with an elevation of 280 ft.
3. No tests have been performed on this day.
4. Poured and filled the HDPE pipe with flowable fill.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Leveling the fill material using the Dozer



Leveling the fill material using the Dozer

Date : 09/22/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 09/22/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 61932
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : SUNNY
Departure Time : 09/22/2023 16:30
ASEC Technician Name : Avinash Bandham



Date : 09/22/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 09/22/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 61932
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : SUNNY
Departure Time : 09/22/2023 16:30
ASEC Technician Name : Avinash Bandham




Poring the flowable fill in the HDPE pipe




Poring the flowable fill in the HDPE pipe

Date : 09/22/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 09/22/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 61932
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : SUNNY
Departure Time : 09/22/2023 16:30
ASEC Technician Name : Avinash Bandham



Monitoring the flow-fill by Terry



Date : 09/22/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 09/22/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 61932
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : SUNNY
Departure Time : 09/22/2023 16:30
ASEC Technician Name : Avinash Bandham



Completely filled HDPE pipe with Flow-fill



Working with flow mixer



Date : 09/22/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 09/22/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 61932
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : SUNNY
Departure Time : 09/22/2023 16:30
ASEC Technician Name : Avinash Bandham



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.