

Date : 09/27/2023  
Project No : 2022C235  
Client Company : Jackson Demolition Service, Inc.  
Arrival Time : 09/27/2023 06:00  
Onsite Hours : 10:30

ASEC Report ID : 62129  
Name of the Project : Plant Gorgas Demolition and Grading  
Project Location : 460 Gorgas Rd, Parrish, AL 35580  
Weather : SUNNY  
Departure Time : 09/27/2023 16:30  
ASEC Technician Name : Avinash Bandham

AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Avinash Bandam visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to monitor, verify and document the ongoing project activities. (Reference drawing E720661 S1 - R8, E720659 S1-R8.)

1. The contractor commenced geo-fabric installation in the basement.
2. Seven Hundred and Thirty-seven tons 825-B Stone has been delivered and placed.
3. No tests have been performed.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Placed the 825-B Stone above the fabric



Placed the 825-B Stone above the fabric



Spread the geo-fabric on the site




Date : 09/27/2023  
Project No : 2022C235  
Client Company : Jackson Demolition Service, Inc.  
Arrival Time : 09/27/2023 06:00  
Onsite Hours : 10:30

ASEC Report ID : 62129  
Name of the Project : Plant Gorgas Demolition and Grading  
Project Location : 460 Gorgas Rd, Parrish, AL 35580  
Weather : SUNNY  
Departure Time : 09/27/2023 16:30  
ASEC Technician Name : Avinash Bandham



Date : 09/27/2023  
Project No : 2022C235  
Client Company : Jackson Demolition Service, Inc.  
Arrival Time : 09/27/2023 06:00  
Onsite Hours : 10:30

ASEC Report ID : 62129  
Name of the Project : Plant Gorgas Demolition and Grading  
Project Location : 460 Gorgas Rd, Parrish, AL 35580  
Weather : SUNNY  
Departure Time : 09/27/2023 16:30  
ASEC Technician Name : Avinash Bandham



Hauling of Stone material



**Ramchandra Mogulla, PE**  
**31220**  
**Senior Engineer**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.