

Date : 09/21/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 09/21/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 61904
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : SUNNY
Departure Time : 09/21/2023 16:30
ASEC Technician Name : Avinash Bandham

AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Avinash Bandam visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to monitor, verify and document the ongoing project activities. (Reference drawing E720661 S1 - R8, E720659 S1-R8.)

1. Hauling in the Basement was performed in section 1 for a lift (10) and Section 2 for a lift (14). Transportation of clay materials has been stopped because of basement has been filled with an elevation of 280 ft.
2. No tests have been performed on this day.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Hauling in Section 1



Hauling in Section 2

Date : 09/21/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 09/21/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 61904
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : SUNNY
Departure Time : 09/21/2023 16:30
ASEC Technician Name : Avinash Bandham



Placed the soil in the basement



Leveled the soil using the roller



Received the crushed concrete to the site

Date : 09/21/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 09/21/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 61904
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : SUNNY
Departure Time : 09/21/2023 16:30
ASEC Technician Name : Avinash Bandham



Leveled the soil using the roller



Ramchandra Mogulla, PE
31220
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.