

Date : 03/06/2023  
Project No : 2023C111  
Client Company : 2MATL  
Arrival Time : 03/06/2023 11:30  
Onsite Hours : 06:00

ASEC Report ID : 57492  
Name of the Project : DOA Fiber Infrastructure Improvements  
Project Location : HJAIA  
Weather : Sunny  
Departure Time : 03/06/2023 17:30  
ASEC Technician Name : Isaac Davis

At the request of the client's representative, AS ENGINEERING AND CONSULTING, LLC (ASEC) representative, Isaac Davis visited the job site to observe and monitor the contractor's work activities from a quality stand point to assure compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

- Concrete was placed within the trench opening for the duct bank.
- Concrete sampling and testing was performed on this day.
- Sample location was DOA-A3D+280. Slump tested appeared to be high and measured 8 inches.
- The contractor representatives were informed of this.
- Strength test results to follow after 28 days.

If you have any questions about our observations or recommendations stated in this report we will be more than glad to discuss them with you.



**Ramchandra R. Mogulla**  
GA P.E. 036021  
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.