

Date : 03/08/2023
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 03/08/2023 07:30
Onsite Hours : 10:30

ASEC Report ID : 57522
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather : Sunny
Departure Time : 03/08/2023 18:00
ASEC Technician Name : Isaac Davis

At the request of the client's representative, AS ENGINEERING AND CONSULTING, LLC (ASEC) representative, Isaac Davis visited the job site to observe and monitor the contractor's work activities from a quality standpoint to assure compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

- In the Afternoon approximately 2pm-3pm while in middle of testing one of BBH's workers hit the cylinders made on 03/07/23 with a Bobcat compact truck loader.
- Cylinders was placed to the side near the protective guard fence
- The cylinders that made full contact with the compact loader to were marked as possibly damaged.
- When the Cylinders were dropped off the lab was informed of the potential issues the cylinders may have

If you have any questions about our observations or recommendations stated in this report we will be more than glad to discuss them with you.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.