

Date : 07/17/2023
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 07/17/2023 7:00
Onsite Hours : 01:00

ASEC Report ID : 60400
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather : sunny
Departure Time : 07/17/2023 8:00
ASEC Technician Name : Aminullah Azimi

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to assure compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

Our representative was on site to observed the placement of concrete for Vault 3. Following a period of standby time, the contractor elected to cancel the concrete placement for the day.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.