

Date : 06/29/2023
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 06/29/2023
Onsite Hours :

ASEC Report ID : 60584
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather : cloudy
Departure Time : 06/29/2023
ASEC Technician Name : Russell Hendrix

Our AS Engineering and Consulting (ASEC) representative was on site for the purpose of providing visual quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

A meeting was requested at vault #2 with QA, ATLNext, and Cheoah on site. The Graded Aggregate Base in the vault #2 area had been previously compacted. There was a concern about using the liquid calcium chloride and getting the needed compaction on the final lift. Upon checking job specifications, it was recommended that granular calcium chloride be used. No further discussions were held.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.