



Date : 03/22/2024
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 03/22/2024 10:00
Onsite Hours :

ASEC Report ID : 67246
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather :
Departure Time : 03/23/2024
ASEC Technician Name : Zabihullah Lodin


As requested, our AS Engineering & Consulting representative was on site to observe the following this day:

- The placement of backfill soils for the DOA Fiber infrastructure from east of N13 and south of runway 27 south continued on this day.
- At the time arrival our representative observed work in progress with duct bank being backfilled and compacted using a trench compactor and density testing performed using a nuclear density gauge.
- Density test results indicate that the compacted materials met the requirement of 90% compaction versus a standard proctor (ASTM 689).



Date : 03/22/2024
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 03/22/2024 10:00
Onsite Hours :

ASEC Report ID : 67246
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather :
Departure Time : 03/23/2024
ASEC Technician Name : Zabihullah Lodin



Date : 03/22/2024
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 03/22/2024 10:00
Onsite Hours :

ASEC Report ID : 67246
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather :
Departure Time : 03/23/2024
ASEC Technician Name : Zabihullah Lodin



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.