



Date : 04/25/2024
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 04/25/2024
Onsite Hours :

ASEC Report ID : 67335
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather :
Departure Time : 04/25/2024
ASEC Technician Name : Zabihullah Lodin

As requested, our AS Engineering & Consulting (ASEC) representative was on site to observe the following:

- The placement of backfill soils for DOA Fiber infrastructure from 70 feet south from the existing comm manhole continued this day.
- At the time of our arrival our representative observed the work in progress with duct bank backfill being placed and compacted using trench compactor equipment. Density testing was performed using a nuclear density gauge.
- Density test results indicate that the compacted materials met the compaction requirement of 90% of a standard proctor (ASTM 689).



Date : 04/25/2024
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 04/25/2024
Onsite Hours :

ASEC Report ID : 67335
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather :
Departure Time : 04/25/2024
ASEC Technician Name : Zabihullah Lodin



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.