

Date : 03/19/2024
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 03/19/2024
Onsite Hours :

ASEC Report ID : 67200
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather :
Departure Time : 03/20/2024
ASEC Technician Name : Zabihullah Lodin

As requested, our AS Engineering & Consulting representative was on site to observe field activities. The following were noted:

- The placement of backfill of soil for DOA Fiber infrastructure from east of N13 and south of runway 27 continued on this day.
- At the time of our arrival, our representative observed work on progress with duct bank backfill being placed and compacted using a trench compactor and tested for compaction using a nuclear density gauge.
- Density result indicated that the compacted materials met the requirement of 90% compaction of a standard proctor (ASTM 689).

Date : 03/19/2024
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 03/19/2024
Onsite Hours :

ASEC Report ID : 67200
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather :
Departure Time : 03/20/2024
ASEC Technician Name : Zabihullah Lodin



Date : 03/19/2024
Project No : 2023C111
Client Company : 2MATL
Arrival Time : 03/19/2024
Onsite Hours :

ASEC Report ID : 67200
Name of the Project : DOA Fiber Infrastructure Improvements
Project Location : HJAIA
Weather :
Departure Time : 03/20/2024
ASEC Technician Name : Zabihullah Lodin



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.