

Date : 05/15/2023
Project No : 2023C118
Client Company : CWM
Arrival Time : 05/15/2023 07:30
Onsite Hours : 11:00

ASEC Report ID : 59314
Name of the Project : Concourse D Widening
Project Location : HJAIA
Weather : sunny/cloudy
Departure Time : 05/15/2023 18:30
ASEC Technician Name : Isaac Davis

As requested, our ASEC representative was on site to observe the placement of concrete for Sequence 3 (between Gates 3 and 5). A sample of fresh concrete was obtained and various testing conducted. Results are stated below.

Project: Concourse D

Location: Sequence 3 between gates 3 and 5

Ambient temperature: 74 degrees F

First sample taken:

Slump = 2 inches

Air Content = 3.5%

Concrete temperature = 70 degrees F

Unit Weight = 146.4 pcf

Test #1 @90 cubic yards:

Slump = 2.5

Air Content = 5%

Concrete temperature = 68 degrees F

Unit Weight = 146.6 pcf

Placed 2 loggers in lane.

#1 logger on north end

#2 logger on south end

Date : 05/15/2023
Project No : 2023C118
Client Company : CWM
Arrival Time : 05/15/2023 07:30
Onsite Hours : 11:00

ASEC Report ID : 59314
Name of the Project : Concourse D Widening
Project Location : HJAIA
Weather : sunny/cloudy
Departure Time : 05/15/2023 18:30
ASEC Technician Name : Isaac Davis



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.