

Date : 06/06/2023
Project No : 2023C144
Client Company : CCG
Arrival Time : 06/06/2023 8:00
Onsite Hours : 07:30

ASEC Report ID : 59720
Name of the Project : Carodel Farms @ Union Church Rd
Project Location : Flowery Branch
Weather : cloudy
Departure Time : 06/06/2023 15:30
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services, visual observation techniques were employed to assure compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

The placement and compaction of backfill soils for Lots #29 and 30 continued this day.

At the time of arrival, our representative observed that work was in progress with lifts being placed to about 1 foot below finished grade and compacted using a P56B compactor.

Density test results will be provided once the Moisture-Density Relationship is performed.



Date : 06/06/2023
Project No : 2023C144
Client Company : CCG
Arrival Time : 06/06/2023 8:00
Onsite Hours : 07:30

ASEC Report ID : 59720
Name of the Project : Carodel Farms @ Union Church Rd
Project Location : Flowery Branch
Weather : cloudy
Departure Time : 06/06/2023 15:30
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.