

Date : 06/27/2023
Project No : 2023C144
Client Company : CCG
Arrival Time : 06/27/2023 08:00
Onsite Hours : 9:00

ASEC Report ID : 60219
Name of the Project : Carodel Farms @ Union Church Rd
Project Location : Flowery Branch
Weather :
Departure Time : 06/27/2023 17:00
ASEC Technician Name : Vidal Shengan

Our AS Engineering and Consulting (ASEC) representative conducted a quality control inspection and testing visit to the Carodel Farms site today. Visual observation techniques were employed to ensure adherence to project drawings/specifications, relevant codes, and materials submittals. The following observations were made during the on-site inspection:

1. Rock Volume Determination:

The determination of rock volume was carried out today, based on the attached drill logs. Both the depths to the top of the rock and termination were recorded. The calculated rock volume is detailed below:

- Volume: 96,768 cubic feet
- Grid Spacing:

- Length: 8 feet
- Width: 8 feet

- Average Thickness: 12 feet
- Total Number of Holes: 126


2. Blast Quantity:

The blasting process was conducted today, with a total quantity of rock shot calculated to be 5223 cubic yards.

We appreciate the opportunity to offer our services for this project. Should you have any questions concerning this report, please do not hesitate to contact us. We are more than happy to discuss this report or any aspect of the project with you.

Attachments:

1. Drill Logs
2. Rock Volume Calculation Data



Vidal Dias
070321636
Project Geologist



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.