

Date : 06/06/2023  
Project No : 2023C144  
Client Company : CCG  
Arrival Time : 06/06/2023 8:00  
Onsite Hours : 07:30

ASEC Report ID : 59714  
Name of the Project : Carodel Farms @ Union Church Rd  
Project Location : Flowery Branch  
Weather : cloudy  
Departure Time : 06/06/2023 15:30  
ASEC Technician Name : Aminullah Azimi

| Test Date                                                 | Test Number | Moisture Content (%) | Dry Density (pcf) | Proctor Number | Max. Dry Density (pcf) | Optimum Moisture (%) | Compaction (%) | Specified Compaction (%) | ASTM Test Method | Pass/Fail |
|-----------------------------------------------------------|-------------|----------------------|-------------------|----------------|------------------------|----------------------|----------------|--------------------------|------------------|-----------|
| 06/06/2023                                                | 1           | 24                   | 96.0              | P-1            | 96.5                   | 22.3                 | 99.5           | 98                       | D6938            | Pass      |
| Location : Lot 30, Elv/Depth :1 foot below finished grade |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Comment :                                                 |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Tested By : Aminullah Azimi Gauge Serial No. : 85759      |             |                      |                   |                |                        |                      |                |                          |                  |           |
| 06/06/2023                                                | 2           | 23.5                 | 99.7              | P-1            | 96.5                   | 22.3                 | 103.3          | 98                       | D6938            | Pass      |
| Location : Lot 29, Elv/Depth :1 foot below finished grade |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Comment :                                                 |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Tested By : Aminullah Azimi Gauge Serial No. : 85759      |             |                      |                   |                |                        |                      |                |                          |                  |           |

**Remark:** Test performed in general accordance with signed referenced ASTM Method.



**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Date : 06/06/2023  
Project No : 2023C144  
Client Company : CCG  
Arrival Time : 06/06/2023 8:00  
Onsite Hours : 07:30

ASEC Report ID : 59714  
Name of the Project : Carodel Farms @ Union Church Rd  
Project Location : Flowery Branch  
Weather : cloudy  
Departure Time : 06/06/2023 15:30  
ASEC Technician Name : Aminullah Azimi

---

**PROCTOR DATA SUMMARY**

| TEST DATE  | PROCTOR ID | MAX DRY DENSITY<br>(pcf) | OPTIMUM MOISTURE (%) | PROCTOR TYPE | SOIL DESCRIPTION       |
|------------|------------|--------------------------|----------------------|--------------|------------------------|
| 05/31/2023 | P-1        | 96.5                     | 22.3                 | Standard     | Red Brown Clayey SSILT |