

Date : 08/17/2023
Project No : 2023C144
Client Company : CCG
Arrival Time : 08/17/2023 12:00
Onsite Hours : 04:00

ASEC Report ID : 60886
Name of the Project : Carodel Farms @ Union Church Rd
Project Location : Flowery Branch
Weather : sunny
Departure Time : 08/17/2023 16:00
ASEC Technician Name : Aminullah Azimi

Our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative, Amin Azimi visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

Our representative observed the drilling of rock and documented the results. Results of rock quantities will be presented in a later report.



Date : 08/17/2023
Project No : 2023C144
Client Company : CCG
Arrival Time : 08/17/2023 12:00
Onsite Hours : 04:00

ASEC Report ID : 60886
Name of the Project : Carodel Farms @ Union Church Rd
Project Location : Flowery Branch
Weather : sunny
Departure Time : 08/17/2023 16:00
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.