

Date : 03/20/2024
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 03/20/2024 12:00
Onsite Hours : 04:00


ASEC Report ID : 65412
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAlA, Atlanta, GA
Weather : sunny
Departure Time : 03/20/2024 16:00
ASEC Technician Name : Aminullah Azimi

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative, Amin Azimi visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

Observed the placement of 8 cubic yards 4000 psi concrete for 27R Slop repair storm water western MH.

Concrete observed on this date appeared to be placed in compliance with project specifications with regard to temperature, air content, and batch to placement time.

In case of any questions or concerns with regards to our observations or recommendations stated in this report we will be more than glad to discuss them with you.



Date : 03/20/2024
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 03/20/2024 12:00
Onsite Hours : 04:00

ASEC Report ID : 65412
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAlA, Atlanta, GA
Weather : sunny
Departure Time : 03/20/2024 16:00
ASEC Technician Name : Aminullah Azimi



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.