

Date : 08/28/2024
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 08/27/2024 19:00
Onsite Hours : 10:00

ASEC Report ID : 69242
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAlA, Atlanta, GA
Weather : Clear sky
Departure Time : 08/28/2024 05:00
ASEC Technician Name : Solomon Cherie

As requested, our AS Engineering & Consulting LLC representative was on site to observe concrete placement. The following were performed this day:

- 1) Moisture tests were taken (for rock and sand materials).
 - 2) Air content tests, concrete temperature, slump and unit weight were taken for Truck #1 sampled.
 - 3) Two sets of seven (7) beams were cast.
 - 4) Stripped one set of seven (7) beams and placed in curing.
- All concrete tests were found to be within job specifications



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.