

Date : 08/24/2024
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 08/24/2024 16:05
Onsite Hours : 9:00

ASEC Report ID : 69227
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAlA, Atlanta, GA
Weather : sunny
Departure Time : 08/25/2024 1:05
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

- At the time of arrival, the first batch of concrete was tested (with WSP, 2Mnext) for slump, air content, temperature of the concrete and unit weight and the results were shared with CW Mathews for the necessary changes. A second round of testing was completed and specimens were cast.
- A second test of concrete (Ramp 7) was initially tested (with WSP, 2Mnext) for slump, air content, temperature of the concrete and unit weight with the results are shared with CW Mathews. A second set of specimens were cast.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.