

Date : 10/10/2024
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 10/10/2024 16:30
Onsite Hours : 04:00

ASEC Report ID : 71216
Name of the Project : Airfield Repairs 2021-23
Project Location : HJAlA, Atlanta, GA
Weather :
Departure Time : 10/10/2024 20:30
ASEC Technician Name : Solomon Cherie

As requested, our AS Engineering & Consulting LLC representative was on site to observe concrete placement. The following were performed this day:

- 1) Moisture tests were taken (for rock and sand materials).
 - 2) Air content tests, concrete temperature, slump and unit weight were taken for Truck sampled.
 - 3) One set of seven (7) beams were cast.
 - 4) Stripped two sets of seven (7) beams and placed in curing.
- All concrete tests were found to be within job specifications.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.