

Date : 06/01/2026
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 05/31/2026 21:30
Onsite Hours : 05:30

ASEC Report ID : 95003
Name of the Project : Airfield Repairs 2021-23
Project Location : HJIA, Atlanta, GA
Weather : Clear
Departure Time : 06/01/2026 03:00
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site to observe the contractor (CWM) and for the observation/testing of cores (sealant in-between cracks). ASEC aided in the collection and logging of 9 cores for the runways. Cores were visually inspected and measured for the thickness of the sealant in-between the joints/cracks. Cores were collected by CWM and 2MNext.

Cores:

R1: 0.5in

R2: 0.6in

R3: 0.5in

9R4: 0.5in

SC #5: 0.25in

SC #6: 0.5in

SC#7: 0.25


SC#8: 0.5in

SC #9: 0.25in

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.

Date : 06/01/2026
Project No : 2023C159
Client Company : CW Matthews
Arrival Time : 05/31/2026 21:30
Onsite Hours : 05:30

ASEC Report ID : 95003
Name of the Project : Airfield Repairs 2021-23
Project Location : HJATA, Atlanta, GA
Weather : Clear
Departure Time : 06/01/2026 03:00
ASEC Technician Name : Sean Willett



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.