Daily Field Report

ASEC Report ID : 60878
Name of the Project : Ashley Falls - Pipe Installation
Project Location : 6031 Wade ORR Road, Flowery Branch, GA
Weather : sunny
Departure Time : 08/15/2023 15:00
ASEC Technician Name : Aminullah Azimi

Date : 08/15/2023
Project No : 2023C179
Client Company : Century Communities Group
Arrival Time : 08/15/2023 8:00
Onsite Hours : 07:00

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to assure compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

The installation of the 15 inch HDPE Storm pipe was observed between MH C8.1 and C8.3, for proper installation, Good connection, Slope, Size of pipe and backfill and then assessed backfill efforts with a probe rod.

The installation appeared to be in accordance with project drawing. Please find the attached pictures of the work performed.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.





Daily Field Report

ASEC Report ID : 60878
Name of the Project : Ashley Falls - Pipe Installation
Project Location : 6031 Wade ORR Road, Flowery Branch, GA
Weather : sunny
Departure Time : 08/15/2023 15:00
ASEC Technician Name : Aminullah Azimi

Date : 08/15/2023
Project No : 2023C179
Client Company : Century Communities Group
Arrival Time : 08/15/2023 8:00
Onsite Hours : 07:00











Daily Field Report

ASEC Report ID : 60878
Name of the Project : Ashley Falls - Pipe Installation
Project Location : 6031 Wade ORR Road, Flowery Branch, GA
Weather : sunny
Departure Time : 08/15/2023 15:00
ASEC Technician Name : Aminullah Azimi

Date : 08/15/2023
Project No : 2023C179
Client Company : Century Communities Group
Arrival Time : 08/15/2023 8:00
Onsite Hours : 07:00



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consultiing LLC.