

Date : 10/25/2023
Project No : 2023C180
Client Company : Artisan Communities
Arrival Time : 10/25/2023 08:00
Onsite Hours : 04:00

ASEC Report ID : 62750
Name of the Project : Lakeside
Project Location : Calhoun
Weather : Sunny
Departure Time : 10/25/2023 12:00
ASEC Technician Name : Vidal Dias

Our ASEC representative was on-site on to verify that surficial soils within Lots #96, 97, and the parking lot area be placed as per project specifications. During the evaluation, the following observations were made:

Soil Evaluation for Lots #96, 97, and Parking Lot Area

Soil Description

- Topsoil mixed with organic materials and roots.

Engineering Observations and Recommendations


- Three test pits were performed to evaluate the extent of the topsoil layer.
- The approximate volume of material removed from the area was 64,500 cubic feet.
- Given the presence of organic materials and roots, it is recommended that these soils be further assessed for suitability as fill material or be removed.

If you have any questions or require further clarification regarding the content of this report, please do not hesitate to get in touch. We are readily available to address any inquiries you may have.



Date : 10/25/2023
Project No : 2023C180
Client Company : Artisan Communities
Arrival Time : 10/25/2023 08:00
Onsite Hours : 04:00

ASEC Report ID : 62750
Name of the Project : Lakeside
Project Location : Calhoun
Weather : Sunny
Departure Time : 10/25/2023 12:00
ASEC Technician Name : Vidal Dias



Vidal Dias

-
Project Geologist



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.