

Date : 11/15/2023
Project No : 2023C180
Client Company : Artisan Communities
Arrival Time : 11/15/2023 08:00
Onsite Hours : 04:00

ASEC Report ID : 62987
Name of the Project : Lakeside
Project Location : Calhoun
Weather : Sunny
Departure Time : 11/15/2023 12:00
ASEC Technician Name : Vidal Dias

On November 15, 2023, the undersigned ASEC representative visited the Lakeside Development site. The purpose of the visit was to inspect the undercutting of topsoil materials in Lots #68, 69, 70, and 71, and to evaluate surficial soils adjacent to Lots #34 through 37, which were in question by the contractor.

Inspection and Findings

Undercutting of Topsoil in Lots #68, 69, 70, and 71


- The topsoil material depths in these lots were visually inspected quantity.
- The undercutting areas are shown in red on the attached drawing.

Evaluation of Soils Behind Lots #34 - 37

- The soils in this area were observed to be tan to brown, Silty fine to medium, and Sand.

Excavation of Large Boulders

- Large boulders were excavated from the road in the area highlighted in yellow on the attached drawing.



Date : 11/15/2023
Project No : 2023C180
Client Company : Artisan Communities
Arrival Time : 11/15/2023 08:00
Onsite Hours : 04:00

ASEC Report ID : 62987
Name of the Project : Lakeside
Project Location : Calhoun
Weather : Sunny
Departure Time : 11/15/2023 12:00
ASEC Technician Name : Vidal Dias



Vidal Dias

-
Project Geologist

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.