


Date : 11/29/2023
Project No : 2023C195
Client Company : Toll Bros. Inc.
Arrival Time : 11/29/2023 08:00
Onsite Hours : 08:00

ASEC Report ID : 63243
Name of the Project : Kimbal Bridge Tract
Project Location : Alpharetta
Weather : Sunny
Departure Time : 11/29/2023 16:00
ASEC Technician Name : Vidal Dias

Test Date	Test Number	Moisture Content (%)	Dry Density (pcf)	Proctor Number	Max. Dry Density (pcf)	Optimum Moisture (%)	Compaction (%)	Specified Compaction (%)	ASTM Test Method	Pass/Fail
11/29/2023	1	31.0	86.6	24207	87.8	31.0	98.6	95	D6938	Pass
Location : Sewer line along Road 'C', Elv/Depth :1112 Comment : see Daily Field Report this day for drawing showing actual test location Tested By : Vidal Dias Gauge Serial No. :										
11/29/2023	2	30.9	86.6	24207	87.8	31.0	98.6	95	D6938	Pass
Location : Sewer line along Road 'C', Elv/Depth :1112 Comment : see Daily Field Report this day for drawing showing actual test location Tested By : Vidal Dias Gauge Serial No. :										
11/29/2023	3	31.0	86.9	24207	87.8	31.0	99.0	95	D6938	Pass
Location : Sewer line along Road 'C', Elv/Depth :1113 Comment : see Daily Field Report this day for drawing showing actual test location Tested By : Vidal Dias Gauge Serial No. :										
11/29/2023	4	30.8	87.2	24207	87.8	31.0	99.3	95	D6938	Pass
Location : Sewer line along Road 'C', Elv/Depth :1113 Comment : see Daily Field Report this day for drawing showing actual test location Tested By : Vidal Dias Gauge Serial No. :										
11/29/2023	5	31.0	87.3	24207	87.8	31.0	99.4	95	D6938	Pass
Location : Sewer line along Road 'C', Elv/Depth :1113 Comment : see Daily Field Report this day for drawing showing actual test location Tested By : Vidal Dias Gauge Serial No. :										
11/29/2023	6	30.9	87.5	24207	87.8	31.0	99.7	95	D6938	Pass
Location : Sewer line along Road 'C', Elv/Depth :1112 Comment : see Daily Field Report this day for drawing showing actual test location Tested By : Vidal Dias Gauge Serial No. :										
11/29/2023	7	31.0	87.6	24207	87.8	31.0	99.8	95	D6938	Pass
Location : Sewer line along Road 'C', Elv/Depth :1112 Comment : see Daily Field Report this day for drawing showing actual test location Tested By : Vidal Dias Gauge Serial No. :										

Remark: Test performed in general accordance with signed referenced ASTM Method.



Vidal Dias

Project Geologist



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Date : 11/29/2023
Project No : 2023C195
Client Company : Toll Bros. Inc.
Arrival Time : 11/29/2023 08:00
Onsite Hours : 08:00

ASEC Report ID : 63243
Name of the Project : Kimbal Bridge Tract
Project Location : Alpharetta
Weather : Sunny
Departure Time : 11/29/2023 16:00
ASEC Technician Name : Vidal Dias

PROCTOR DATA SUMMARY

TEST DATE	PROCTOR ID	MAX DRY DENSITY (pcf)	OPTIMUM MOISTURE (%)	PROCTOR TYPE	SOIL DESCRIPTION
10/10/2023	24207	87.8	31.0	Standard	Red to Brown Micaceous Silty CLAY
10/10/2023	24208	110.4	16.3	Standard	Tan to Brown Micaceous Silty SAND
10/10/2023	24209	111.6	16.5	Standard	Reddish Brown Micaceous Sandy SILT