


Date : 02/05/2024
Project No : 2023C195
Client Company : Toll Bros. Inc.
Arrival Time : 02/05/2024 8:30
Onsite Hours : 03:00

ASEC Report ID : 63976
Name of the Project : Kimbal Bridge Tract
Project Location : Alpharetta
Weather : sunny
Departure Time : 02/05/2024 11:30
ASEC Technician Name : Aminullah Azimi

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

- We recommended to the contractor to undercut unsuitable soils from various locations in the retaining wall 7 footing.
- Observed undercutting, backfilling and compaction with suitable soils, using a trench compactor.



Kenneth Mosman

Kenneth Mosman

Date : 02/05/2024
Project No : 2023C195
Client Company : Toll Bros. Inc.
Arrival Time : 02/05/2024 8:30
Onsite Hours : 03:00

ASEC Report ID : 63976
Name of the Project : Kimbal Bridge Tract
Project Location : Alpharetta
Weather : sunny
Departure Time : 02/05/2024 11:30
ASEC Technician Name : Aminullah Azimi

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.