

Date : 11/28/2023
Project No : 2023C201
Client Company : Artisan Built Communities
Arrival Time : 11/28/2023 12:00
Onsite Hours : 04:00

ASEC Report ID : 63147
Name of the Project : Jasons Walk - Era Drive
Project Location : Era Drive, Cumming, GA
Weather : Partly Cloudy
Departure Time : 11/28/2023 16:00
ASEC Technician Name : Vidal Dias

The undersigned ASEC representative was on site as requested by the Contractor to observe storm drain and soil backfill placement. Visual observation techniques were employed to evaluate work in-place for general compliance with the Project Plans, Specifications, Codes and Standards, and Material Submittals.

Soil Placement and Compaction

- **Location:** Lots #8, 9, and 10.
- **Activity Observed:** Soil placement to final grade.
- **Compaction Tests:** Conducted on each lot, with the results detailed below.

Storm Drain Placement

- **Location:** Along Ava Court, work area highlighted in blue on attached drawing.
- **Activity Observed:** Placement of storm drains.
- **Compliance:** The storm drains were observed during placement.

If you have any questions or require further clarification regarding the content of this report, please do not hesitate to get in touch. We are readily available to address any inquiries you may have. We appreciate the opportunity to contribute to this project.



Date : 11/28/2023
Project No : 2023C201
Client Company : Artisan Built Communities
Arrival Time : 11/28/2023 12:00
Onsite Hours : 04:00

ASEC Report ID : 63147
Name of the Project : Jasons Walk - Era Drive
Project Location : Era Drive, Cumming, GA
Weather : Partly Cloudy
Departure Time : 11/28/2023 16:00
ASEC Technician Name : Vidal Dias



Vidal Dias

-
Project Geologist

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.