


Date : 12/29/2023
Project No : 2023C201
Client Company : Artisan Built Communities
Arrival Time : 12/29/2023 08:00
Onsite Hours : 04:00

ASEC Report ID : 63570
Name of the Project : Jasons Walk - Era Drive
Project Location : Era Drive, Cumming, GA
Weather :
Departure Time : 12/29/2023 12:00
ASEC Technician Name : Vidal Dias

The undersigned ASEC representative was on site as requested by the client and/or contractor to observe contractor's field activities. Visual observation techniques were employed to evaluate work in-place for general compliance with the Project Plans, Specifications, Codes and Standards, and Material Submittals.

During this visit, a trash pit was discovered while placing the 18" pipe from AA11 to AA12. The area is highlighted in red on the attached drawing. The contractor has begun excavating the unsuitable soils from this area.



Vidal Dias

Vidal Dias

Project Geologist

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.