

Date : 05/31/2024
Project No : 2023C206
Client Company : CWM-JVTECH
Arrival Time : 05/31/2024 6:00
Onsite Hours : 9:00

ASEC Report ID : 66821
Name of the Project : Concourse D Widening
Project Location : HJAIA
Weather : sunny
Departure Time : 05/31/2024 15:00
ASEC Technician Name : Aminullah Azimi

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative, Amin Azimi visited the job site to visually observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made during our evaluation:

- A pre-pour and concrete observation was performed in concourse D, panels 21, 23 and panel 31, on this day. The contractor completed rebar and dowel placement for these panels,
- The writer visually inspected the installation and setup of these lanes and advised the contractor representatives of any minor corrections that were required.
- Contractor cleaned loose rock and debris and puddles of water from the base.
- Dowel bars have epoxy. Embedment depth was found to be 15" into concrete.
- The reinforcing steel was checked for correct size, number of bars, location of bars, spacing, cleanliness, support against displacement, splicing, clearance and steel grade. Based on visual observations and field measurements, the reinforcing steel at the utility panel, appeared to be acceptable for size, spacing and quantity.
- Concrete observed on this date appeared to be placed in compliance with project specifications with regard to temperature, slump, air content, and batch to placement time
- Our representative along with ATLQA and ATLNext representatives and CWM rep signed the pre-pour card.



Daily Field Report

Date : 05/31/2024
Project No : 2023C206
Client Company : CWM-JVTECH
Arrival Time : 05/31/2024 6:00
Onsite Hours : 9:00

ASEC Report ID : 66821
Name of the Project : Concourse D Widening
Project Location : HJAlA
Weather : sunny
Departure Time : 05/31/2024 15:00
ASEC Technician Name : Aminullah Azimi

 **C. R. Matheson**
Pre-Pair Checklist

Checklist # _____
 Date 3/30/2024
 Location WY 100, Loc. 111, 101
 Surveyor W. J. Matheson

Observer(s) _____ Date _____

Observer	1st Pair	2nd Pair	3rd Pair	4th Pair	5th Pair	6th Pair	7th Pair	8th Pair
Observer 1	1.1	1.2	1.3	1.4	1.5	1.6	1.7	1.8
Observer 2	2.1	2.2	2.3	2.4	2.5	2.6	2.7	2.8
Observer 3	3.1	3.2	3.3	3.4	3.5	3.6	3.7	3.8
Observer 4	4.1	4.2	4.3	4.4	4.5	4.6	4.7	4.8
Observer 5	5.1	5.2	5.3	5.4	5.5	5.6	5.7	5.8
Observer 6	6.1	6.2	6.3	6.4	6.5	6.6	6.7	6.8
Observer 7	7.1	7.2	7.3	7.4	7.5	7.6	7.7	7.8
Observer 8	8.1	8.2	8.3	8.4	8.5	8.6	8.7	8.8
Observer 9	9.1	9.2	9.3	9.4	9.5	9.6	9.7	9.8
Observer 10	10.1	10.2	10.3	10.4	10.5	10.6	10.7	10.8
Observer 11	11.1	11.2	11.3	11.4	11.5	11.6	11.7	11.8
Observer 12	12.1	12.2	12.3	12.4	12.5	12.6	12.7	12.8
Observer 13	13.1	13.2	13.3	13.4	13.5	13.6	13.7	13.8
Observer 14	14.1	14.2	14.3	14.4	14.5	14.6	14.7	14.8
Observer 15	15.1	15.2	15.3	15.4	15.5	15.6	15.7	15.8
Observer 16	16.1	16.2	16.3	16.4	16.5	16.6	16.7	16.8
Observer 17	17.1	17.2	17.3	17.4	17.5	17.6	17.7	17.8
Observer 18	18.1	18.2	18.3	18.4	18.5	18.6	18.7	18.8
Observer 19	19.1	19.2	19.3	19.4	19.5	19.6	19.7	19.8
Observer 20	20.1	20.2	20.3	20.4	20.5	20.6	20.7	20.8
Observer 21	21.1	21.2	21.3	21.4	21.5	21.6	21.7	21.8
Observer 22	22.1	22.2	22.3	22.4	22.5	22.6	22.7	22.8
Observer 23	23.1	23.2	23.3	23.4	23.5	23.6	23.7	23.8
Observer 24	24.1	24.2	24.3	24.4	24.5	24.6	24.7	24.8
Observer 25	25.1	25.2	25.3	25.4	25.5	25.6	25.7	25.8
Observer 26	26.1	26.2	26.3	26.4	26.5	26.6	26.7	26.8
Observer 27	27.1	27.2	27.3	27.4	27.5	27.6	27.7	27.8
Observer 28	28.1	28.2	28.3	28.4	28.5	28.6	28.7	28.8
Observer 29	29.1	29.2	29.3	29.4	29.5	29.6	29.7	29.8
Observer 30	30.1	30.2	30.3	30.4	30.5	30.6	30.7	30.8
Observer 31	31.1	31.2	31.3	31.4	31.5	31.6	31.7	31.8
Observer 32	32.1	32.2	32.3	32.4	32.5	32.6	32.7	32.8
Observer 33	33.1	33.2	33.3	33.4	33.5	33.6	33.7	33.8
Observer 34	34.1	34.2	34.3	34.4	34.5	34.6	34.7	34.8
Observer 35	35.1	35.2	35.3	35.4	35.5	35.6	35.7	35.8
Observer 36	36.1	36.2	36.3	36.4	36.5	36.6	36.7	36.8
Observer 37	37.1	37.2	37.3	37.4	37.5	37.6	37.7	37.8
Observer 38	38.1	38.2	38.3	38.4	38.5	38.6	38.7	38.8
Observer 39	39.1	39.2	39.3	39.4	39.5	39.6	39.7	39.8
Observer 40	40.1	40.2	40.3	40.4	40.5	40.6	40.7	40.8
Observer 41	41.1							



Kenneth Masmen

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.