

Date : 10/05/2024
Project No : 2024C105
Client Company : CW Matthews
Arrival Time : 10/05/2024 06:30
Onsite Hours : 03:00

ASEC Report ID : 70891
Name of the Project : West Curb_HJAIA CWM
Project Location : HJAIA
Weather :
Departure Time : 10/05/2024 09:30
ASEC Technician Name : Solomon Cherie

As requested, our AS Engineering & Consulting LLC representative was on site to observe concrete placement. The following were performed this day:

- 1) Moisture tests were taken.
 - 2) Air content tests, concrete temperature, slump and unit weight were taken for the first truck sampled.
 - 3) One set of eleven (11) beams were cast.
- All concrete tests were found to be within job specifications.



One set of 11 beams

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.