

Density Test Report

Date : 05/01/2024
Project No : 2024C112
Client Company : SR Homes
Arrival Time : 05/01/2024
Onsite Hours :

ASEC Report ID : 66363
Name of the Project : Sterlington
Project Location : Canton
Weather : overcast
Departure Time : 05/01/2024
ASEC Technician Name : Russell Hendrix

Test Date	Test Number	Moisture Content (%)	Dry Density (pcf)	Proctor Number	Max. Dry Density (pcf)	Optimum Moisture (%)	Compaction (%)	Specified Compaction (%)	ASTM Test Method	Pass/Fail
05/01/2024	1	13	94.0	P-01	94.8	25.0	99.2	95	D6938	Pass
Location : 7a-12 to Lot #1 lateral, Elv/Depth :-2 feet from finished grade										
Comment :										
Tested By : Russell Hendrix Gauge Serial No. : 30942										
05/01/2024	2	13.2	94.5	P-01	94.8	25.0	99.7	95	D6938	Pass
Location : 7a-12 to Lot #1 lateral, Elv/Depth :-1 foot from finished grade										
Comment : future Roadway section will also be proof-rolled at a later date.										
Tested By : Russell Hendrix Gauge Serial No. : 30942										

Remark: Test performed in general accordance with signed referenced ASTM Method.

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Date : 05/01/2024
Project No : 2024C112
Client Company : SR Homes
Arrival Time : 05/01/2024
Onsite Hours :

ASEC Report ID : 66363
Name of the Project : Sterlington
Project Location : Canton
Weather : overcast
Departure Time : 05/01/2024
ASEC Technician Name : Russell Hendrix

PROCTOR DATA SUMMARY

TEST DATE	PROCTOR ID	MAX DRY DENSITY (pcf)	OPTIMUM MOISTURE (%)	PROCTOR TYPE	SOIL DESCRIPTION
02/19/2024	P-01	94.8	25.0	Standard	Brown Silty SAND
05/13/2024	P-02	105.9	18.8	Standard	Brown Silty SAND