

Date : 07/16/2024
Project No : 2024C112
Client Company : SR Homes
Arrival Time : 07/16/2024
Onsite Hours :

ASEC Report ID : 67974
Name of the Project : Sterlington
Project Location : Canton
Weather : overcast
Departure Time : 07/16/2024
ASEC Technician Name : Russell Hendrix

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made during our evaluation:

Graded Aggregate Base (GAB) Testing Report

Upon arrival, it was observed that the graded aggregate base (GAB) was not ready for testing. Approximately 50% of the GAB of the future roadway had been placed (see photo) but not fully compacted. As a result, no testing was performed on this day.



Starting location of GAB placement for 7/16

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.