

Date : 07/16/2024
Project No : 2024C112
Client Company : SR Homes
Arrival Time : 07/16/2024
Onsite Hours :

ASEC Report ID : 67974
Name of the Project : Sterlington
Project Location : Canton
Weather : overcast
Departure Time : 07/16/2024
ASEC Technician Name : Russell Hendrix

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made during our evaluation:

Graded Aggregate Base (GAB) Testing Report

Upon arrival, it was observed that the graded aggregate base (GAB) was not yet ready for testing. Approximately 50% of the GAB of the future roadway had been placed (see photo) but not fully compacted. As a result, no testing was performed on this day.



Starting location of GAB placement for 7/16

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.