

Date : 07/12/2024
Project No : 2024C112
Client Company : SR Homes
Arrival Time : 07/12/2024
Onsite Hours :

ASEC Report ID : 67904
Name of the Project : Sterlington
Project Location : Canton
Weather : sunny
Departure Time : 07/12/2024
ASEC Technician Name : Russell Hendrix

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Proof-Roll Inspection Report

A proof-roll was performed using a loaded tandem-axled dump truck across the compacted soils along both sides of the future roadway (see attached photo). The county inspector, client, and grading foreman were present for the inspection. No severe pumping and/or rutting was observed, and all parties were in agreement with the results.



GAB delivery ticket with weight



Loaded Tandem Dump truck

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.