


Date : 05/30/2024
Project No : 2024C116
Client Company : Peeples Owner, LLC
Arrival Time : 05/30/2024
Onsite Hours :

ASEC Report ID : 67342
Name of the Project : Peeples Valley Rd, Overlook at Pettit
Project Location : Cartersville
Weather : overcast
Departure Time : 05/30/2024
ASEC Technician Name : Russell Hendrix

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

Summary

Following a discussion with the ASEC engineer, a meeting was held with the foreman at the Peeples Valley project site to address and continue with recommendations concerning the drainage of the existing detention pond. The purpose of the meeting was to plan the necessary actions to fix the affected areas. Remediation was not observed at this time.



Affected area from detention pond



detention pond

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.