

Date : 06/03/2024
Project No : 2024C116
Client Company : Peeples Owner, LLC
Arrival Time : 06/03/2024 08:00
Onsite Hours : 08:00

ASEC Report ID : 67366
Name of the Project : Peeples Valley Rd, Overlook at Pettit
Project Location : Cartersville
Weather : sunny
Departure Time : 06/03/2024 16:00
ASEC Technician Name : Marteze Jeter

At the request of the client's representative, our AS ENGINEERING AND CONSULTING, LLC (ASEC) representative visited the job site to observe the contractor's work activities from a quality standpoint to verify compliance with project drawings/specifications, applicable codes, and materials submittals and conducted QC testing per the project drawings and specifications. The following observations were made on site this shift:

Our representative observed the contractor continue to place and compact fill in Section 1. Probing with a 3/8" diameter probe rod was performed during fill placement to verify subgrade stability following compaction.

Observations:

1. **Backfilling Activities:** Contractor compacted Section 1 in 8-inch lifts and compacted.

Conclusion: The ongoing backfilling activities are progressing as planned.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.