

Date : 06/17/2024
Project No : 2024C116
Client Company : Peeples Owner, LLC
Arrival Time : 06/17/2024 08:30
Onsite Hours : 08:30

ASEC Report ID : 67085
Name of the Project : Peeples Valley Rd, Overlook at Pettit
Project Location : Cartersville
Weather : Sunny
Departure Time : 06/17/2024 17:00
ASEC Technician Name : Fawad Shagiwal

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services.

The following observations were observed on the site this day:

- The placement and compaction of backfill for Section 2 was in progress using CP54B, RA30, D51PX and CAT330 equipment.
- At the time of arrival our representative observed that work was in progress in Section 2 with a 2-foot lift being placed and compacted using CP54B and D51PX equipment.
- Proof-rolling was conducted for Section 3. Our representative observed that surficial soils were pumping/rutting in some areas of the section with the underlying soils high in moisture content.



Date : 06/17/2024
Project No : 2024C116
Client Company : Peeples Owner, LLC
Arrival Time : 06/17/2024 08:30
Onsite Hours : 08:30

ASEC Report ID : 67085
Name of the Project : Peeples Valley Rd, Overlook at Pettit
Project Location : Cartersville
Weather : Sunny
Departure Time : 06/17/2024 17:00
ASEC Technician Name : Fawad Shagiwal



Date : 06/17/2024
Project No : 2024C116
Client Company : Peeples Owner, LLC
Arrival Time : 06/17/2024 08:30
Onsite Hours : 08:30

ASEC Report ID : 67085
Name of the Project : Peeples Valley Rd, Overlook at Pettit
Project Location : Cartersville
Weather : Sunny
Departure Time : 06/17/2024 17:00
ASEC Technician Name : Fawad Shagiwal



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.