

Date : 08/02/2024
Project No : 2024C195
Client Company : CWM
Arrival Time : 07/31/2024 18:00
Onsite Hours : 08:00

ASEC Report ID : 68345
Name of the Project : Ramp 21 Replacement
Project Location : HJAIA
Weather : Cloudy
Departure Time : 08/01/2024 02:00
ASEC Technician Name : Solomon Cherie

As requested, our AS Engineering & Consulting LLC representative was on site to observe the following:

- 1) Stripped seven beams cast yesterday and placed into curing.
- 2) Completed moisture tests for #67 & #4 sand materials.
- 3) Air content, concrete temperature, slump and unit weight tests were performed for the first truck placement.
- 4) Five air content tests were performed for concrete sampled throughout the pour. The first four tests indicated air contents higher than job specifications.
- 5) The casting of two sets of beams for 189 and 405 cubic yards placed.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.