

Date : 08/07/2024
Project No : 2024C195
Client Company : CWM
Arrival Time : 08/06/2024 17:00
Onsite Hours : 11:15

ASEC Report ID : 68500
Name of the Project : Ramp 21 Replacement
Project Location : HJAIA
Weather :
Departure Time : 08/07/2024 04:15
ASEC Technician Name : Solomon Cherie

As requested, our AS Engineering & Consulting LLC representative was on site to perform the following:

- 1) Moisture tests were performed on sand materials placed.
- 2) Slump tests and one set of 5 cylinders were cast.
- 3) Air, slump, temperature and unit weight tests for the 1st truck of the normal batch were performed.
- 4) The above tests and two sets of seven beams were cast from trucks #23 & #56.

There was some delay in concrete placement throughout the pour due to equipment issues.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.