

Date : 08/21/2024
Project No : 2024C195
Client Company : CWM
Arrival Time : 08/20/2024 18:00
Onsite Hours : 07:45

ASEC Report ID : 68994
Name of the Project : Ramp 21 Replacement
Project Location : HJAIA
Weather : Clear sky
Departure Time : 08/21/2024 01:45
ASEC Technician Name : Solomon Cherie

As requested, our AS Engineering & Consulting LLC representative was on site to observe site activities. The following were performed this day:

- 1) Moisture tests were taken.
- 2) Stripped concrete beams from yesterday and placed in curing.
- 2) Air content tests, concrete temperature, slump and unit weight were taken for the first truck sampled.
- 3) One set of beams were cast from Truck #15.
- 4) Cast one set of 4 6" x 12" cylinders from the low slump, low energy mix.

All concrete tests were found to be within job specifications.



Date : 08/21/2024
Project No : 2024C195
Client Company : CWM
Arrival Time : 08/20/2024 18:00
Onsite Hours : 07:45

ASEC Report ID : 68994
Name of the Project : Ramp 21 Replacement
Project Location : HJAIA
Weather : Clear sky
Departure Time : 08/21/2024 01:45
ASEC Technician Name : Solomon Cherie



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.