

Date : 04/30/2026
Project No : 2024C217
Client Company : Artisan
Arrival Time : 04/23/2026 08:00
Onsite Hours : 06:30

ASEC Report ID : 93780
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 04/23/2026 14:30
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date our representative was on site to observe the curb contractor make recommended repairs requested by the county for the raised island pork chop located on Seven Hills Boulevard exiting from Shelby Parkway. The contractor extended the poured end by extending the length westward and placing reinforcing steel (#4 rebar doubled in place) as recommended and poured 3000 psi concrete. The finished product appeared suitable for requirements and approved by Paulding County.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Finished product extending the pork chop end as recommended.



Date : 04/30/2026
Project No : 2024C217
Client Company : Artisan
Arrival Time : 04/23/2026 08:00
Onsite Hours : 06:30


ASEC Report ID : 93780
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 04/23/2026 14:30
ASEC Technician Name : Clyde Smith



Pouring concrete at repaired area



Added reinforcing #4 bars doubled in place of #5 bars.



Date : 04/30/2026
Project No : 2024C217
Client Company : Artisan
Arrival Time : 04/23/2026 08:00
Onsite Hours : 06:30

ASEC Report ID : 93780
Name of the Project : Naturewalk - 7 Hills Amenities
Project Location : Dallas
Weather : cloudy
Departure Time : 04/23/2026 14:30
ASEC Technician Name : Clyde Smith



Saw cut existing end to extend longer to prevent
left turn

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.