

Date : 10/17/2024
Project No : 2024C297
Client Company : Artisan
Arrival Time : 10/17/2024
Onsite Hours :

ASEC Report ID : 75760
Name of the Project : Nature Walk - Footing Inspections
Project Location : Dallas
Weather :
Departure Time : 10/17/2024
ASEC Technician Name : Vamsi Polisetty

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Nature walk: Lots #1055 & #1056

- Upon arrival, the contractor was engaged in undercutting unsuitable (gray, organic matter) and a burn pit found at 12ft from the ground level of Lot #1055 and #1056.
- A soil sample was taken for performing a Moisture-Density Relationship (proctor) from the nearby undisturbed soils.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.

DCP LOCATION:

Lot #,
North/South/Cen
ter etc

Lot 94 Front

Depth (feet)	Set 2"	N 1.75"	Description
1		7	Red, Sandy SILT.
2		7	Red, Sandy SILT.
3		4	Red, Sandy SILT.
4		5	Red, Sandy SILT.
5			

Kenneth Mosman

Kenneth Mosman
Project Professional



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.