Daily Field Report

ASEC Report ID : 64434
Name of the Project : Traditions Pod X
Project Location : Hoschton
Weather : sunny
Departure Time : 03/29/2024
ASEC Technician Name :

Date : 02/29/2024
Project No : 2024G135
Client Company : Pulte
Arrival Time : 03/29/2024
Onsite Hours :

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Location: 2020 Cotton Gin, Traditions

DCPs requested at gravel parking lot (from surface no footings):

depth (ft) / hits / Soil Type

Southwest Corner (off of Gravel pad)

1, 0, White minteral

2, 6, Red sandy silt

3, 10, Red sandy silt

4, 11, Red sandy silt

5, 10, Red sandy silt

6, 14, Red & Yellow Sandy silt

Southeast Corner

1, 0, Gravel

2,13, Red sandy silt

3, AR, Rock (possibly PWR)

Offset

3, AR, Rock (Possibly PWR)

Northwest Corner

1,0, Gravel

2,15, Red sandy silt

3,12, Red sandy silt

4,11, Red sandy silt

5,14, Brown sand

6,12, Dark Red sandy silt

Northeast

1,0, Gravel

2,12, Red sandy silt

3, AR offset

3,11, Red sandy silt

4,12, Red sandy silt

5,11, Red sandy silt

6,11 Red sandy silt



AS Engineering and Consulting LLC

Daily Field Report

ASEC Report ID : 64434
Name of the Project : Traditions Pod X
Project Location : Hoschton
Weather : sunny
Departure Time : 03/29/2024
ASEC Technician Name :

Date : 02/29/2024
Project No : 2024G135
Client Company : Pulte
Arrival Time : 03/29/2024
Onsite Hours :

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consultiing LLC.