

Date : 05/15/2026
Project No : 2025C187
Client Company : CWM
Arrival Time : 05/15/2026 08:00
Onsite Hours : 06:30

ASEC Report ID : 94525
Name of the Project : Lee Gilmer Memorial Airport - Rehab
Terminal Area Apron PH 3
Project Location : Gainesville
Weather : Sunny
Departure Time : 05/15/2026 14:30
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.


Our ASEC representative was on site to observe the contractor (CWM) and for the observation/testing of the placement of asphalt. The contractors continued to mill/place tack and fabric on pre-existing asphalt for Phase 2. Asphalt placement was visually observed and spot checked with density testing during installation. No adjustments to the rolling pattern were made. Any cracking that was present was discussed with UES and CWM. Density testing was performed and test results were provided to the contractor.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 05/15/2026
Project No : 2025C187
Client Company : CWM
Arrival Time : 05/15/2026 08:00
Onsite Hours : 06:30

ASEC Report ID : 94525
Name of the Project : Lee Gilmer Memorial Airport - Rehab
Terminal Area Apron PH 3
Project Location : Gainesville
Weather : Sunny
Departure Time : 05/15/2026 14:30
ASEC Technician Name : Sean Willett



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.