

Date : 05/13/2026
Project No : 2026C101
Client Company : Artisan
Arrival Time : 05/13/2026 09:30
Onsite Hours : 00:30

ASEC Report ID : 94265
Name of the Project : Seven Hills PHASE 13, UNIT 4 Lots
Project Location : Dallas
Weather : sunny
Departure Time : 05/13/2026 10:00
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date our representative met with our client Mr. Calvin Mcwain at Rosemary Landing to discuss observations required to issue building lot certifications for Lots #1073, 1074 and 1083. It was recommended to have DCP tests performed (dynamic cone penetrometer) on all lots in question. One lot has been stripped of vegetation, and the remaining two lots are still grassed.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Building lots on Rosemary Landing





AS Engineering
and Consulting LLC

Daily Field Report

Date : 05/13/2026
Project No : 2026C101
Client Company : Artisan
Arrival Time : 05/13/2026 09:30
Onsite Hours : 00:30

ASEC Report ID : 94265
Name of the Project : Seven Hills PHASE 13, UNIT 4 Lots
Project Location : Dallas
Weather : sunny
Departure Time : 05/13/2026 10:00
ASEC Technician Name : Clyde Smith

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.